Timeline of Maintenance Activities on General Sullivan Bridge (NH Bridge 200/023)

| Date(s) | Source | Action/Subject | Funding/ Cost |
|--------------------|--|--|---------------|
| May 15, 1984 | Inter-department Memorandum, Special Bridge Projects | Subject: Spaulding Tpke, US 4, NH 16 Southbound over Little Bay; notes repairs needs and general maintenance | |
| May 18, 1984 | Entry in 1984-2007 Maintenance Record | Reattached insp. Plates on sidewalk + placed plates over hole in easterly sidewalk. | |
| May 23, 1984 | Inter-department Memorandum, Bridge Maintenance | Subject: Various Minor Repairs; notes record of maintenance of GSB (reference letter May 15, 1984) | |
| August 18, 1984 | Entry in 1984-2007 Maintenance Record | Cleaning + mortaring joints on piers. | |
| September 1, 1984 | Entry in 1984-2007 Maintenance Record | Mortaring joints on piers. | |
| September 8, 1984 | Entry in 1984-2007 Maintenance Record | Mortaring joints on piers. | |
| September 15, 1984 | Entry in 1984-2007 Maintenance Record | Comp. mortaring joints on piers. Greased rollers. | |
| April 1, 1986 | Department of Public Works and Highways Letter response to private citizen | Individual requested road maintenance of GSB since he frequently bicycles over the GSB. | |
| August 13, 1988 | Entry in 1984-2007 Maintenance Record | Greasing roller & set floatation rafts | |
| August 20, 1988 | Entry in 1984-2007 Maintenance Record | Completed greasing roller essem. & install new tide gauges on Pier. | |
| August 27, 1988 | Entry in 1984-2007 Maintenance Record | Working on tide gauges. | |
| June 10, 1989 | Entry in 1984-2007 Maintenance Record | Assisting inspection team. Crew #11. | |
| June 11, 1989 | Inter-department Memorandum, Bureau of Bridge Design | Subject: GSB Use for Emergency Detour; makes note of deterioration of the top surface of the concrete slab hidden by the asphalt pavement being present in "28 of 84 test holes in 1974". Notes delamination in several areas on underside of the deck. Notes deck is being raised off stringers due to layers of rust between top flanges and concrete deck. (Describes more re: condition.) Ends with action needed to allow single-lane of light traffic to use the bridge. | |
| June 17, 1989 | Entry in 1984-2007 Maintenance Record | Assisting inspection team. Crew #11. | |
| June 24, 1989 | Entry in 1984-2007 Maintenance Record | Chipping and removing sidewalk on U/S side at east end. Forming sidewalk and welding bridge rail at various locations. Crew #11. | |
| July 1, 1989 | Entry in 1984-2007 Maintenance Record | Continued chipping deteriorated areas of U/S catwalk, formed and poured first section. Crew #11. | |
| July 8, 1989 | Entry in 1984-2007 Maintenance Record | Stripping and forming alternate sections of sidewalk on U/S side. Also installing steel plates at expansion joints and bolting down. Crew #11. | |
| July 15, 1989 | Entry in 1984-2007 Maintenance Record | Stripping and forming alternate sections of sidewalk on U/S side. Crew #11. | |
| July 22, 1989 | Entry in 1984-2007 Maintenance Record | Stripping and forming alternate sections of sidewalk on U/S side. Also started on deck areas. Crew #11. | |
| July 29, 1989 | Entry in 1984-2007 Maintenance Record | Removing deteriorated sections of deck, forming and pouring. Crew #11. | |
| August 5, 1989 | Entry in 1984-2007 Maintenance Record | Formed, placed re-steel, and poured various deck sections. Crew #11. | |
| August 12, 1989 | Entry in 1984-2007 Maintenance Record | Formed, placed re-steel, and poured various deck sections. Crew #11. | |
| August 19, 1989 | Entry in 1984-2007 Maintenance Record | Formed, placed re-steel, and poured various deck sections. Crew #11. | |
| August 30, 1989 | Entry in 1984-2007 Maintenance Record | Completed forming, placed re-steel, and pouring various deck sections. Crew #11. | |

| November 24, 1990 | Entry in 1984-2007 Maintenance Record | Assisting in Inspection. Crew #12. | |
|---------------------|--|---|--------------|
| December 1, 1990 | Entry in 1984-2007 Maintenance Record | Assisting in inspection. Crew #12. | |
| May 18, 1991 | Entry in 1984-2007 Maintenance Record | Repair fellow guard and lighting. Crew #11. | |
| June 22, 1991 | Entry in 1984-2007 Maintenance Record | Install tide guages. Crew #11. | |
| August 3, 1991 | Entry in 1984-2007 Maintenance Record | Install tide guages. Crew #11. | |
| 0 | Entry in 1984-2007 Maintenance Record | Replace tide guage on General Sullivan Bridge. | |
| May 27, 1995 | Entry in 1984-2007 Maintenance Record | Subject: GSB Bridge Coating Evaluation; notes condition of existing coating and steel | |
| | Inter-department Memorandum, Bureau of Materials and Research | corrosion. Memo concludes with recommendation to "blast down to bare metal and then | |
| June 13, 1996 | | repaint with an organic zinc primer, an epoxy intermediate coat and a top coat of | |
| | | polyurethane." | |
| March 21, 1998 | Entry in 1984-2007 Maintenance Record | Replace navigation light bulbs on U/S side of bridge. | |
| August 22, 1000 | Entry in 1984-2007 Maintenance Record | Assist Turnpike's electrician in troubleshooting navigation light electrical problem. Replace | |
| August 22, 1998 | | and splice wire as needed. | |
| | Inter-department Memorandum, Bureau of | Subject: GSB - Condition of Deck and Navigation Lights; memo addresses concerns regarding | |
| October 1, 1998 | Turnpikes | bridge condition; outlines two key problems with lights and GSB structure. | |
| | | | |
| October 0, 1009 | Site photographs with "repaired" hand-written | South abutment and backwall spalling, exposed rebar; asphalt hole at joint patch; steel plate settled 4"; heavy spalling/exposed rebar at north end; delaminations over walkway; asphalt | |
| October 9, 1998 | notes on a few of the photos. | hole at joint patch | |
| | | Subject: GSB; concerns regarding navigational lighting system and deterioration of the steel | |
| November 23, 1998 | Inter-department Memorandum, Bureau of | superstructure and concrete deck; proposed cost estimates to maintain the GSB (est. \$20,000 | |
| 1000011001 20, 2000 | Turnpikes, Bridge Maintenance, and Bridge Design | per year). | |
| | NHDOT Request for Project Authorization - by Bridge | | |
| March 4, 1999 | | Description of Work: repair south abutment | |
| March 4, 1999 | Entry in 1984-2007 Maintenance Record | Repair south abutment face at seat area as needed. Repair deck areas for pedestrian access as | |
| Waren 4, 1999 | Entry III 1984-2007 Maintenance Record | needed. | |
| | Entry in 1984-2007 Maintenance Record | Move equipment and materials to project. Remove rip-rap at face of south abutment and | |
| March 18, 1999 | | remove deteriorated concrete at same. Haul concrete debris from project. | |
| | | | |
| March 25, 1999 | Entry in 1984-2007 Maintenance Record | Remove deteriorated concrete at south abutment face. Haul concrete debris from project. | |
| | - , | | |
| March 29, 1999 | Inter-department Memorandum, Bureau of Public | Subject: GSB - Navigation Lights; cost estimate to complete work to replace the navigation | Estimated at |
| Widi Cli 29, 1999 | Works | lights | \$45,000.00 |
| Annii 1, 1000 | | Erect Spider staging at east end of bridge. Construct temporary shield to catch demolition | |
| April 1, 1999 | Entry in 1984-2007 Maintenance Record | debris and remove shoring at east end. | |
| | Entry in 1984-2007 Maintenance Record | Place re-steel at east abutment face. Remove pavement and deteriorated concrete at deck | |
| April 8, 1999 | | side of east expansion joint; place re-steel, set forms, and place concrete at same. Place and | |
| | , | removed steel traffic plates daily. Haul concrete debris from project. | |
| | | | |
| April 15, 1999 | Entry in 1984-2007 Maintenance Record | Remove barricades at easterly expansion joint and open to pedestrian traffic. Set forms and | |
| April 13, 1333 | | place concrete at east abutment face (two lifts). Remove staging at east end of bridge. | |
| April 15, 1999 | Entry in 1984-2007 Maintenance Record | | |

| April 22, 1999 | Entry in 1984-2007 Maintenance Record | Place backfill and rip-rap at E abutment. Repair areas of structural steel section loss as needed. Apply anti-spall compund. Paint bridge shoes and bearing plates at east end. Clean up project site. Move materials and equipment from project. SUSPENDED | |
|-------------------|---|---|---|
| May 25, 1999 | Letter regarding navigational lights. | Letter of approval from USCG to NHDOT for proposed replacement of navigational lights, with attached placement plan. | |
| June 3, 1999 | Bid Results: Replace Navigation Lights, GSB | Yates Electric Service Inc., Farmington, NH | |
| March 6, 2000 | Entry in 1984-2007 Maintenance Record | Repair float, dock and walkway as needed to keep in service. Assist with installation and removal. | |
| March 9, 2000 | Entry in 1984-2007 Maintenance Record | Move equipment and materials to project. Reinforce bridge rail to support Spider staging. | |
| March 16, 2000 | Entry in 1984-2007 Maintenance Record | Reinforce bridge rail and install Spider staging and work platforms at west side of a second joint. Install false work to catch concrete removal debris. Remove expansion joint plates and adjacent pavement ay same. | |
| March 23, 2000 | Entry in 1984-2007 Maintenance Record | Remove deteriorated concrete from ends of deck section at expansion joint #2. Place reinforcing steel and set forms at same. | |
| March 30, 2000 | Entry in 1984-2007 Maintenance Record | Place concrete at west end of deck at expansion joint #2. Remove deteriorated concrete east end of deck section at expansion joint #2. Place reinforcing steel and set forms at same. | |
| April 6, 2000 | Entry in 1984-2007 Maintenance Record | Place concrete at west end of deck at expansion joint #2. Remove staging and false work at same. Remove inland tide gauge to be replaced at a later date. | |
| April 13, 2000 | Entry in 1984-2007 Maintenance Record | Replace inland tide gauge. PROJECT SUSPENDED. | |
| April 27, 2000 | Entry in 1984-2007 Maintenance Record | Install Dow-Corning sealant at expansion joint #2. | |
| June 5, 2000 | northeast decking depressed area; torn compression seal; damaged rail and post at west | Site photographs with "repaired" hand-written note on damaged rail photo. | |
| June 8, 2000 | Entry in 1984-2007 Maintenance Record | Remove existing D/S tide gauge and bracket. Install new bracket anchors and install tide gauge. | |
| February 27, 2001 | Entry in 1984-2007 Maintenance Record | Repair deck and joints to keep in service for pedestrian traffic. | , |
| March 1, 2001 | Entry in 1984-2007 Maintenance Record | Move equipment and materials to project. | |
| March 8, 2001 | Entry in 1984-2007 Maintenance Record | Move equipment and materials to project. | |
| March 15, 2001 | Entry in 1984-2007 Maintenance Record | Assist Crew 15 with erection of staging for deck repairs. | |
| March 15, 2001 | Entry in 1984-2007 Maintenance Record | Move equipment and materials to project. Reinforce bridge rail as needed and erect staging for deck repairs. | |
| March 22, 2001 | Entry in 1984-2007 Maintenance Record | Assist Crew 15 with erection of staging for deck repairs. | |
| March 22, 2001 | Entry in 1984-2007 Maintenance Record | Erect Spider staging and debris shield at north end expansion joint. Remove deteriorated concrete and expansion joint steel at same. | |
| March 29, 2001 | Entry in 1984-2007 Maintenance Record | Remove asphalt and deteriorated concrete at expanse joints as needed. Set forms at same. | |
| April 5, 2001 | Entry in 1984-2007 Maintenance Record | Place concrete at north end expansion joint. Move equipment and materials from project. | |
| April 19, 2001 | Entry in 1984-2007 Maintenance Record | Remove Spider staging from bridge. Move equipment from project. | |

| January 11, 2002 | Inter-department Memorandum, Office of Bridge Design | Subject: GSB Possible Temporary Measures; describes inspection results from 1989 and 1991; summarizes 1991 report repair estimates (in 1991 and 2002 \$), including: (1) New deck, guardrails & pedestrian rails, pavement, exterior stringers, steel repairs, seismic isolation bearings, paint removal, cleaning and repainting. (2) All the above plus pier encasements. (3) All the above plus new piers. (4) New replacement structure. | |
|-------------------|--|--|--|
| March 27, 2002 | Entry in 1984-2007 Maintenance Record | Remove and replace expansion joints, repair deck and sidewalk. | |
| April 4, 2002 | Entry in 1984-2007 Maintenance Record | Move materials and equipment to project. Hang Spider Staging at expansion joint as work platform. | |
| April 11, 2002 | Entry in 1984-2007 Maintenance Record | Clean tide gauge and replace navigation lights as necessary. Remove expansion joint sliding plate and deteriorated concrete adjacent to it. | |
| April 18, 2002 | Entry in 1984-2007 Maintenance Record | Form, place reinforcement steel and concrete at second expansion joint from the north. | |
| April 25, 2002 | Entry in 1984-2007 Maintenance Record | Remove and replace deteriorated concrete adjacent to sidewalk. | |
| May 2, 2002 | Entry in 1984-2007 Maintenance Record | Remove deck joint falsework and Spider Staging. Move materials and eqipment from project. | |
| May 9, 2002 | Entry in 1984-2007 Maintenance Record | Remove concrete spalls on the under side of deck on the main span over river traffic. | |
| March 18, 2004 | Entry in 1984-2007 Maintenance Record | Replace missing electrical pull box covers as necessary. | |
| August 11, 2005 | Entry in 1984-2007 Maintenance Record | Repair navigation lights. | |
| October 24, 2005 | Inter-department Memorandum, Bureau of Highway Design: Recommended Preferred Alternative | Describes GSB rehabilitation steps and costs, associated with the DEIS Preferred Alternative. | |
| July 12, 2007 | Entry in 1984-2007 Maintenance Record | Replace navigational light bulbs as necessary and secured access covers on sidewalks. | |
| November 18, 2010 | Construction of Dover approach (before/after) | Site photographs. | |
| November 14, 2011 | Construction of Dover approach (before/after) | Site photographs. | |
| March 6, 2012 | Construction of Dover approach (before/after) | Site photographs. | |
| November 26, 2012 | Section on east has weight limit of 12 people max. | Site photograph. | |
| November 7, 2013 | Beam #2 heat straightened | Site photograph. | |
| March 30, 2015 | Chain link fence in place for safety | Site photograph. | |
| Unknown | NHDOT Request for Project Authorization - by Bridge Maintenance (NOTE: approval line is unsigned) | Description of Work: remove and replace expansion joints; repair deck and sidewalk. Includes three site photographs from 1998, showing spalling and delaminations on northern end of GSB. | |
| | | | |